

## **TunerPro Additional Bluetooth Connection Information**

**Just some additional information from Craig's tutorials and information. This is assuming that you have everything in the car installed correctly and you have picked a data file, XDF definition and the correct datastream. Take these directions for what they are, the rantings of a beginner! This is how I was able to get connected with Bluetooth.**

**Both switches on Autoprom towards the inside.**

**Turn key to on position and plug-in USB cord.**

**Go to Device Manager and open up USB serial port.**

**Try to pick a comport 8 or below.**

**Under advanced settings change data rate to 64 (lowest setting).**

**Change latency timer to 1 and uncheck serial enumerator. Then minimize device manager.**

**Unplug USB cord wait a few seconds and plug-in again.**

**Start TunerPro and under tools, preferences pick the ALDL/emulation tab and pick AutoProm for interface type.**

**Close TunerPro and start car ,unplug USB, plug-in again start TunerPro and you should be able to connect.**

**Start ALDL to see if values for correct data stream are registering. If they are then close TunerPro and unplug USB.**

**Connect with blue radios in Bluetooth devices, default as pairing code.**

**Start up TunerPro and you should be connected wirelessly.**